




Lathe

Autobar 300 & 400

MAIN POWER
 300 spec. 110V, 220V or 440V
 AT 2 AMPS single phase
 400 spec. 220V AT 7 AMPS
 1 or 3 phase

LEGEND	
	CLOSED CONTACT
	OPEN CONTACT



CONTACTS SHOWN IN RUN STATE.

IF LOADER POWER IS USED THEN: THE CONTACT BELOW MUST BE DRY CONTACTS.